

Use this worksheet as a guide for conducting gas station vapor recovery tests in ORCAA's jurisdiction (Clallam, Grays Harbor, Jefferson, Mason, Pacific, & Thurston Counties)

Step 1: Work through the flowchart (reverse side) to determine what baseline tests are required for Stage I vapor recovery systems associated with underground gasoline storage tanks.

Step 2: Determine if the station has a NOC with ORCAA (call/email our office if you are unsure). **All tests listed in a NOC must be performed in addition to baseline tests identified by this flowchart.** If a testing frequency required by a NOC does not match the frequency identified by this flowchart, the facility must follow the testing schedule that is the most stringent.

Questions?

Olympic Region Clean Air Agency
(360) 539-7610
2940 Limited Lane
Olympia, WA 98502

All tests listed in a NOC must be performed in addition to baseline tests identified by this flowchart

